


BMD 101 Welding Procedure (Ver 1.0)

1. Pin Connector Define



电极 1 : Sensor 1

电极 2 : Sensor 2

屏蔽线 : Shield Wiring


电池盒 红线: Battery “+”

电池盒 黑线: Battery “-”



只需接信号线: connect with Signal wiring without shield wiring .

2. After Welding




4. Bluetooth Paired

- 1) Install TOSHIBA Driver , Do not put BT Dongle into USB port until the information come out .
- 2) After installed please restart PC
- 3) Please open the icon on the right of corner , then click below :



4) Clip 下一步 (Next Step)





5) pin 码 0000




5. Open "CardioChip"


1) Click "Continue"




2) Choice "40" COM to connection



3) If it successful at the left of corner, Enter to Application



4) Put the left & Right Finger to each of sensor tip (1.2) , Signal as below :



5) Once the wave reversal please exchange right & Left finger to touch sensor .