



Inspection No: XXXXX  
 Questionnaire: Architectural  
 Recorder: Last Name, First Name  
 Last Edited By: Last Name, First Name

Subject: Building Name - Building #  
 Time In: YYYY-MM-DD HH:MM:SS  
 Time Out: YYYY-MM-DD HH:MM:SS  
 Last Edited: YYYY-MM-DD HH:MM:SS

**Question****Answer**

## Asset Data

## Overall Building Comments

## Comments

Building 1 was Built in 1967. Building is in Good to Fair Condition. Community Center / Attain Lab at 1st Floor - (Abandoned Space)  
 Building Components Upgraded : Main Roof, Roof Drains, Bulkhead walls - Repointing, Chimney, Exterior Walls - Repointing in 2016.  
 \* The Infrared Thermography Roof Assessment Report for this building indicates possible wet insulation below the roofing. Refer to the Infrared Thermography Roof Assessment Report for this building for additional information.

## Property Contacts

## Name

Selwayne Burke

## Position

Superintendent

## Name

Verhonda Johnson

## Position

Building Manager

## Total Area (Square Feet)

230279

## Total Apartment Area (Square Feet)

194968

## Total Number of Apartments

234

## Total Stories (Floors) Excluding Basements

24

## Building Photo 1

Yes

## Photo Location

Main Entrance 303

## Photo Frame



## Building Photo 2

Yes

## Photo Location

Along Vernon Avenue



Inspection No:	XXXXX	Subject:	Building Name - Building #
Questionnaire:	Architectural	Time In:	YYYY-MM-DD HH:MM:SS
Recorder:	Last Name, First Name	Time Out:	YYYY-MM-DD HH:MM:SS
Last Edited By:	Last Name, First Name	Last Edited:	YYYY-MM-DD HH:MM:SS


Question	Answer
----------	--------

Photo Frame



Building Templates


Roof Plan Template



Exterior Inspected

Areaway Drains	Inspected
Condition Rating	5- POOR
Deficiency?	Yes
Deficiency	Clogged

Deficiency Location/Instance



Deficiency Quantity	9
Quantity UOM	EACH
Potential Action	Repair
Urgency Of Action	1- Immediate
Purpose Of Action	4- Restore
Photo?	Yes
Photo Location	Facade E