



PT LINES SHOULD BE LOOPED BETWEEN CONNECTORS. NO PT LINES ON 18 PIN CONNECTOR

comma.ai
you can copy this!

9

TITLE: Toyota_Harness_board

Design by:

REV:

Date: 3 Jul 2024 21:31:54

Sheet: 1/1