


## Motor on/off circuit F802



Cut trace between J1-pin 6 and 94 pin 2.

Solder side put wire IC39 pin 8 to 94 pin 2.

Place pullup 100 Ohm from motor on to +5V at last drive.

Title		
Size B	Number	Revision
Date:	6-Dec-2023	Sheet of
File:	C:\Program Files\Design Explorer 99 SE\Examples\B02.dbb	