




# 1. Table of Contents (This Page)


Created on Tue May 16 14:30:32 2017


- 2. top
- 3. bottom
- 4. outline
- 5. plated-drill
- 6. componentmask
- 7. soldermask
- 8. topsilk
- 9. bottomsilk
- 10. topassembly
- 11. bottomassembly
- 12. fab
































There are 7 different drill sizes used in this layout, 107 holes total

| Symbol | Diam. (Inch) | Count | Plated? |
|--------|--------------|-------|---------|
| Y      | 0.028        | 44    | YES     |
| +      | 0.030        | 14    | YES     |
| x      | 0.032        | 5     | YES     |
| o      | 0.035        | 6     | YES     |
| □      | 0.038        | 28    | YES     |
| ⌘      | 0.042        | 6     | YES     |
| ⌀      | 0.120        | 4     | YES     |

Title: MotorControl - Fabrication Drawing

Author: Corey Sauer

Date: Tue 16 May 2017 08:30:32 PM GMT UTC



Board outline is the centerline of this path