

Vehicle Damage Insurance Claim

Driver Information

Name:	Mallory Lucas
License No:	S10270423
DOB:	01/16/1977
Address:	02798 Amy Common, Jordanview, ME 34044
Class:	CDL
Endorsements:	Four Wheeler

Vehicle Damage Assessment

Car Make	Toyota
Car Model	Camry
Car Color	Silver
Damage Details	The front bumper is severely damaged, with visible cracks and dents. The headlight assembly is also damaged, and the front fender is bent. The front tire and wheel are intact but may have sustained internal damage.
Damage Level	high
Repair Recommendation	Recommend a full front-end inspection and potential replacement of the bumper, headlight assembly, and fender. Check for any internal damage to the tire and wheel.
Claim Value (\$)	\$8,523

Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Recommend a full front-end inspection and potential replacement of the bumper, headlight assembly, and fender. Check for any internal damage to the tire and wheel.. The estimated severity level is categorized as 'high', with an estimated claim value of \$8,523. Please review and approve for claim processing.