

Vehicle Damage Insurance Claim

Driver Information

Name:	Savannah Matthews
License No:	S35097735
DOB:	01/28/1992
Address:	505 Jeffrey Turnpike Apt. 883, North Elizabethborough, OR 98789
Class:	M
Endorsements:	Four Wheeler

Vehicle Damage Assessment

Car Make	Opel
Car Model	Vectra
Car Color	Silver
Damage Details	The rear bumper is detached, the tail light is broken, and the rear quarter panel is dented.
Damage Level	high
Repair Recommendation	Recommend replacing the rear bumper, tail light, and repairing the dented quarter panel. Check for any underlying damage to the chassis.
Claim Value (\$)	\$2,774

Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Recommend replacing the rear bumper, tail light, and repairing the dented quarter panel. Check for any underlying damage to the chassis.. The estimated severity level is categorized as 'high', with an estimated claim value of \$2,774. Please review and approve for claim processing.