

Components:

tenda ac7 firmware 15.03.06.44
tenda ac7 1.0

Description:

Tenda AC7 V1.0 V15.03.06.44 found a buffer overflow caused by the timeZone parameter in the form_fast_setting_wifi_set function, which can cause RCE.

Main problems:

120 "Buffer Copy without Checking Size of Input ('Classic Buffer Overflow')"