

## Components:

tenda ac9 firmware 15.03.05.14

tenda ac9 1.0

## Description:

In Tenda AC9 v1.0 V15.03.05.14\\_multi, the cloneType parameter of /goform/AdvSetMacMtuWan has a stack overflow vulnerability, which can lead to remote arbitrary code execution.

## Main problems:

787 "Out-of-bounds Write"