

Components:

```
dlink dir-825\gf gf
dlink dir-825\ac e
dlink dir-825 r1 firmware *
dlink dir-825 r1
dlink dir-825\ac e1a
dlink dir-825\a d1a
dlink dir-825\acf f1
```

Description:

An issue was discovered on D-Link DIR-825 R1 devices through 3.0.1 before 2020-11-20. A buffer overflow in the web interface allows attackers to achieve pre-authentication remote code execution.

Main problems:

119 no CWE Description available