

## Components:

## Description:

NETGEAR XR1000 before 1.0.0.74, XR1000v2 before 1.1.0.22, and XR500 before 2.3.2.134 allow remote code execution by unauthenticated users.

## Main problems:

94 "Improper Control of Generation of Code ('Code Injection')"