

Components:

tenda_ac9 firmware 15.03.05.14

tenda_ac9 1.0

Description:

In Tenda AC9 v1.0 V15.03.05.14_multi, the cloneType parameter of /goform/AdvSetMacMtuWan has a stack overflow vulnerability, which can lead to remote arbitrary code execution.

Main problems:

787 "Out-of-bounds Write"