

Components:

dlink dns-320 firmware 2.06b01

dlink dns-320 ax

Description:

D-Link DNS-320 FW v2.06B01 Revision Ax is affected by command injection in the system_mgr.cgi component, which can lead to remote arbitrary code execution.

Main problems:

78 "Improper Neutralization of Special Elements used in an OS Command ('OS Command Injection')"