

Components:

```
automationdirect p3-550e -  
automationdirect p3-550e firmware 4.1.1.10  
automationdirect p3-550e firmware 1.2.10.9
```

Description:

A code injection vulnerability exists in the scan_lib.bin functionality of AutomationDirect P3-550E 1.2.10.9. A specially crafted scan_lib.bin can lead to arbitrary code execution. An attacker can provide a malicious file to trigger this vulnerability.

Main problems:

345 no CWE Description available