

Jackson Place Complex Photograph Collection

An inventory of the Jackson Place Complex Photograph Collection at DC Public Library

This finding aid was produced using ArchivesSpace on September 27, 2018.

English

Describing Archives: A Content Standard

Stage

Table of Contents

| | |
|----------------------------------|---|
| Summary Information | 3 |
| Administrative Information | 3 |
| Controlled Access Headings | 3 |
| Collection Inventory | 4 |
| Series 1 | 4 |

Summary Information

| | |
|----------------------------------|---------------------------------------------|
| Repository: | Stage |
| Title: | Jackson Place Complex Photograph Collection |
| ID: | P021 |
| Date [inclusive]: | 1988 |
| Physical Description: | 1 box |
| Language of the Material: | English |
| Language of the Material: | English |
| Language of the Material: | English |

[^ Return to Table of Contents](#)

Administrative Information

Publication Statement

Stage

[^ Return to Table of Contents](#)

Controlled Access Headings

- Photographs

Collection Inventory

| Series 1 | | |
|-------------------------------------------------------------------------------------|-----------|----------|
| Title/Description | Instances | |
| Architectural model of the Jackson Place Complex, undated | Box 1 | Folder 1 |
| Scope and Contents (Photocopy, 3 copies) | | |
| General view of Jackson Place from Lafayette square, undated | Box 1 | Folder 2 |
| Scope and Contents (3 copies) | | |
| General view of Jackson Place upper floors and roofs from Lafayette square, undated | Box 1 | Folder 3 |
| General view of Jackson Place from Lafayette square, undated | Box 1 | Folder 4 |
| Scope and Contents (3 copies) | | |
| General view of the rear of Jackson Place, undated | Box 1 | Folder 5 |
| Scope and Contents (3 copies) | | |
| General view of plaza behind Jackson Place, undated | Box 1 | Folder 6 |
| Scope and Contents (3 copies) | | |
| Rear steps of building #734, undated | Box 1 | Folder 7 |
| Scope and Contents (3 copies) | | |
| Detail and planter box behind #722, undated | Box 1 | Folder 8 |
| Scope and Contents (3 copies) | | |
| Typical interior wall damage caused by leaking gutters, undated | Box 1 | Folder 9 |

Scope and Contents

(3 copies)

East half of #708 parapet wall, undated

Box 1

Folder 10

Scope and Contents

(3 copies)

Detail of paint on parapet wall, undated

Box 1

Folder 11

Scope and Contents

(3 copies)

"Walking parapet of #708 from roof of #712, undated

Box 1

Folder 12

Scope and Contents

(3 copies)

Failed parging at truncated chimney of #712, undated

Box 1

Folder 13

Scope and Contents

(3 copies)

Metal barrel dormers at #712, undated

Box 1

Folder 14

Scope and Contents

(3 copies)

Detail of typical patching and repair of #712, undated

Box 1

Folder 15

Scope and Contents

(3 copies)

South face of parapet between #708 and #712, undated

Box 1

Folder 16

Scope and Contents

(3 copies)

South face of #716 chimney, undated

Box 1

Folder 17

Scope and Contents

(3 copies)

East facing dormers of #718, undated

Box 1

Folder 18

Scope and Contents

(3 copies)

| | | |
|--------------------------------------------------------------|-------|-----------|
| Detail of gutter intersection between #716 and #718, undated | Box 1 | Folder 19 |
|--------------------------------------------------------------|-------|-----------|

Scope and Contents

(3 copies)

| | | |
|---------------------------------------------|-------|-----------|
| West-facing mansard roof of #726-A, undated | Box 1 | Folder 20 |
|---------------------------------------------|-------|-----------|

Scope and Contents

(3 copies)

| | | |
|------------------------------------------------------|-------|-----------|
| Typical sealant joint failure of cast stone, undated | Box 1 | Folder 21 |
|------------------------------------------------------|-------|-----------|

Scope and Contents

(3 copies)

| | | |
|----------------------------------------------|-------|-----------|
| East facing dormer cladding at #736, undated | Box 1 | Folder 22 |
|----------------------------------------------|-------|-----------|

Scope and Contents

(3 copies)

| | | |
|-------------------------------------------------------------------|-------|-----------|
| Built in gutter and gravel-stop details at #734 and #736, undated | Box 1 | Folder 23 |
|-------------------------------------------------------------------|-------|-----------|

Scope and Contents

(3 copies)

| | | |
|----------------------------------------|-------|-----------|
| Early surface-rusting at #740, undated | Box 1 | Folder 24 |
|----------------------------------------|-------|-----------|

| | | |
|-----------------------------------------|-------|-----------|
| Roof of #744 looking northeast, undated | Box 1 | Folder 25 |
|-----------------------------------------|-------|-----------|

Scope and Contents

(3 copies)

| | | |
|--------------------------------------|-------|-----------|
| South end of Jackson Place, ca. 1920 | Box 1 | Folder 26 |
|--------------------------------------|-------|-----------|

Scope and Contents

(photocopy, 3 copies)

| | | |
|-----------------------------------------------|-------|-----------|
| Blair-Lee Houses and Renwick Gallery, undated | Box 1 | Folder 27 |
|-----------------------------------------------|-------|-----------|

Scope and Contents

(photocopy, 3 copies)

| | | |
|---------------------------------------|-------|-----------|
| North face of building #736, ca. 1902 | Box 1 | Folder 28 |
|---------------------------------------|-------|-----------|

Scope and Contents

(photocopy, 3 copies)

Building #734 and #736, ca. 1920

Box 1

Folder 29

Scope and Contents

(photocopy, 3 copies)

Building #722, ca. 1930

Box 1

Folder 30

Scope and Contents

(photocopy, 3 copies)

Jackson Place looking southwest, ca. 1934

Box 1

Folder 31

Scope and Contents

(photocopy, 3 copies)

[^ Return to Table of Contents](#)