

## **L3800**

Version: 2.02.18.05 **LATEST**

Date: 24 May 2018

### **New Features**

1. None.

### **Bugs Fixed**

1. None.

### **Modification**

1. Removal of tamper processing.
2. For production to print:
  - a. Reader number
  - b. Card number

### **Compatibility List**

1. This firmware require to be use with P1 software version 3.14g.17.11 and onward.

Note:

1. This phase 2 firmware version is to differentiate HADP from OSDP. Since HADP reader(from HID) is obsolete.

## **L3800**

Version: 2.01.17.11

Date: 22 November 2017

### **New Features**

1. Support SR100 and SR200.

### **Bugs Fixed**

1. None.

### **Modification**

1. None

### **Compatibility List**

1. This firmware require to be use with P1 software version 3.14f.17.11 and onward.

Note:

1. This phase 2 firmware version is to differentiate HADP from OSDP. Since HADP reader(from HID) is obsolete.

## **L3800**

Version: 1.08.15.06

Date: 01 June 2015

### **New Features**

1. None

### **Bugs Fixed**

1. Suprema Reader unable to communicate with controller.

### **Modification**

1. None

### **Compatibility List**

1. This firmware require to be use with P1 software version 3.12.14.06(RC.27s) onward

## **L3800**

Version: 1.07.14.06

Date: 27 June 2014

### **New Features**

1. Support for HADP reader(HID RKL55) with LCD display.

### **Bugs Fixed**

1. None

### **Modification**

1. None

### **Compatibility List**

1. This firmware require to be use with P1 software version 3.12.14.06(RC.27s) onward

## **L3800**

Version: 1.03.10.10[1.03.10.10]

Date: 26 October 2010

### **New Features**

1. None

### **Bugs Fixed**

1. Solve controller time will revert to 2001 January 1<sup>st</sup> when the following condition has been meet :
  - a. Current controller date is larger than 19<sup>th</sup> or controller month is larger than September.
  - b. A controller reset happen.

### **Modification**

1. None

### **Compatibility List**

1. This firmware require to be use with P1 software version 3.08.10.08 onward

## **L3800**

Version: 1.02.10.09[1.02.10.09]

Date: 21 October 2010

### **New Features**

1. None

### **Bugs Fixed**

1. None

### **Modification**

1. Put a short delay in replying to solve for PCC1 send command fail.

### **Compatibility List**

1. This firmware require to be use with P1 software version 3.08.10.08 onward

## **L3800**

Version: 1.01.10.09[1.01.10.09]

Date: Never Release Officially

### **New Features**

1. None

### **Bugs Fixed**

1. None

### **Modification**

1. Controller ignore weigand input if incoming total weigand bit is not match with controller setting. Controller will no longer log transaction (Incorrect Card Format) when incoming total weigand bit is not match.

### **Compatibility List**

1. This firmware require to be use with P1 software version 3.08.10.08 onward

## **L3800**

Version: 1.00.10.08[1.00.10.08]

Date: 13 August 2010

### **New Features**

1. Support features available in L2000
2. Enable single triggering for all the floor
3. Support a total of 136floor (first slave with 8 floor, subsequent maximum of 8 slave with 16 floor)

### **Bugs Fixed**

1. None

### **Modification**

1. This model natively support 64Mb internal storage

### **Compatibility List**

1. This firmware require to be use with P1 software version 3.08.10.08 onward