

Prepared (also subject responsible if other) Rajasekar R		No.		
Approved	Checked	Date 27-03-2020	Rev Ver1.0	Reference

MOP of Port Mode Mismatch Alarm for Huawei Site

Table of contents

Activity Description.....	2
Flow Chart	3
Activity Details.....	4


Prepared (also subject responsible if other) Rajasekar R		No.		
Approved	Checked	Date 27-03-2020	Rev Ver1.0	Reference

Activity Description

Alarm Name	1. PORTMODE_MISMATCH
Alarm Description	1. Port Working Mode Mismatch
Possible Causes	1.Port Issue. 2.Cable issue. 3.Port settings issue.

Prepared (also subject responsible if other) Rajasekar R		No.		
Approved	Checked	Date 27-03-2020	Rev Ver1.0	Reference

Flow Chart



Prepared (also subject responsible if other) Rajasekar R		No.		
Approved	Checked	Date 27-03-2020	Rev Ver1.0	Reference

Activity Details

Port Issue: HW port may be faulty in RTN or Mux End, Need to change.

Cable Issue: After replacing cable still alarm exist, cable need to replace.

Port Settings: Need to configure the same settings at both end.