


2024.1.31


1.修复A.VCC

2.删除多余的二极管



低级错误，此处应该引入A.VCC

TITLE: Sheet_1		REV: 1.0
	Company: Your Company	Sheet: 1/1
	Date: 2023-11-09	Drawn By: Denjhang





TITLE: Sheet_1		REV: 1.0
		Sheet: 1/1
Company: Your Company		Date: 2023-11-09 Drawn By: Denjhang



SSG在过下拉电阻之前，禁止接电容
此处参考RC2014-YM2149的黄金比例立体声混音

TITLE: Sheet_1		REV: 1.0
	Company: Your Company	Sheet: 1/1
	Date: 2023-11-20 Drawn By: Denjhang	

