
















1n电容位置放置错误  
60TK焊盘间距过大  
2023.12.21  
1.焊盘间距已修复，需要再次测量实物  
2.Vbias已添加  
3.滤波电容已更换







去掉二极管，那个会引起压降







TITLE: Sheet_1		REV: 1.0
嘉立创EDA	Company: Your Company	Sheet: 1/1
	Date: 2023-12-15	Drawn By: Denjhang



TITLE: Sheet_1		REV: 1.0
	Company: Your Company	Sheet: 1/1
	Date: 2023-12-15 Drawn By: Denjhang	



TITLE: Sheet_1		REV: 1.0
	Company: Your Company	Sheet: 1/1
	Date: 2023-12-15 Drawn By: Denjhang	