

NORTHWEST DRIZZLE

P.O. Box 77777
Puyallup, WA 98373

Mail To: Current Resident
PO Box 666
DEADWOOD, WA
98765

PROPERTY INFORMATION

NA

Location: 3377 Happy Valley Rd
DEADWOOD
Tax ID: 12345678912

Use:

GENERAL SYSTEM TYPE: FAST to UV to pressure drainfield

ON ID: 654321

Fold
Here

ON-SITE WASTEWATER TREATMENT SYSTEM INSPECTION REPORT

Inspected: 05/16/2008 - Inspection Type: INTERMITTENT - Correction Status: No corrections needed

Company:
NORTHWEST DRIZZLE

Work Performed By:
Burt Durp

Submitted 06/12/2008 by:
Cora Borax

Fold
Here

COMMENTS & GENERAL INSPECTION NOTES**No Deficiencies Noted****GENERAL SITE & SYSTEM CONDITIONS**

The General Site and System Conditions were:	Fully Inspected
All Components accessible for maintenance, secure and in good condition:	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (roads, buildings, etc.) onto component(s):	NO
Component settling problems observed:	NO
Abnormal ponding present for one or more of the disposal components:	NO
Subsurface components adequately covered	YES
Site maintenance required (e.g. Landscape maintenance) If yes, describe in comments:	NO

CONTROL PANEL INSPECTION DETAIL**Panel: Control 1 (Time Dosed)**

Manufacturer: Model: Serial#:

This component was:	Fully Inspected	
Control Panel functioning as intended:	Yes	
Control Panel Usage:	Standard	
Alarm functioning as intended:	Yes	
Number of pumps that this panel controls:	1	
Pumps operate independently (Daily flow averages are not accumulative):	True	

Pump 1 - Demand Dosed

PUMP GPM:	Tank Gal/Inch:	Inches Dropped:	Test Time (hh/mm/ss):	00/1/0	Current GPM:	Last GPM:		
Operational Settings:	CURRENT	LAST	OVERRIDE	Counters:	CURRENT	LAST	PERIOD	GPD AVG
Cycles Per Day:				Off Counter:				
Gallons Per Cycle:				Cycle Counter:				0.00
ON Time (hh/mm/ss):				Flow Meter:		0.00		0.00
OFF Time (hh/mm/ss):				ETM reading:				0.00
Current Setting GPD:	0.00						Days in period:	

ONSITE SEWAGE SYSTEM INSPECTION DETAIL**TANK: Trash Tank**

This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
All required baffles in place (N/A = No baffles required):	YES	

Effluent level within operational limits (if NO explain in comments):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	6	
Compartment 1 Sludge accumulation (Inches, if other specify):	8	
Pumping needed:	NO	
Approximate Gallons to be pumped (if needed) by Certified Pumper:		
Aerobic Treatment Unit: ATU		
Manufacturer: Bio-Microbics, Inc. Model: MicroFAST 0.5		
This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Aerobic Mechanism appears to be functioning per manufacturers specifications:	YES	
ATU serviced per manufacturers requirements including cleaning of applicable filter(s):	YES	
Trash Compartment solids accumulation within operational limits per manufacturer (n/a = no trash compartment):	YES	
Aerobic Chamber solids accumulation within manufacturer operational limits (n/a = no aerobic chamber):	YES	
Clarifying Chamber solids accumulation within manufacturer operational limits (n/a = no clarifying chamber):	YES	
Pumping needed:	NO	
Approximate Gallons to be pumped (if needed) by Certified Pumper:		
TANK: Pump Tank		
This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping needed:	NO	
Approximate Gallons to be pumped (if needed) by Certified Pumper:		
Pump: Effluent Pump		
This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Controls functioning:	YES	
Pump Vault Filter cleaned (N/A = not present):	N/A	
Disinfection: Ultra Violet		
Manufacturer: The Disinfecter Model: Disinfecter		
This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Alarm mechanism functioning as intended:	YES	
UV bulb cleaned:	YES	
Drainfield: Pressure		
This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Lateral lines flushed:	NO	
Average squirt height (if performed) (feet, if other specify):		
Ponding present? If YES explain in comments:	NO	