

Very Real Site Report for testing



House A is progressing well

Roof is up.

Walls are Ready for external render.

Windows are installed.

Current access to the house is unsafe.

A new safer ramp should be installed.

Scaffolding is not tied properly in in some parts.

Missing some windowsills need more.