


Front side



Roof Condition: Seems OK

Windshield Condition: Seems OK

Hood Condition: Major damage


Grill Condition: Major damage

Front Bumper Condition: Major damage

Mirrors Condition: Seems OK

Front Lights Condition: Minor damage

Back side



Rear Window Condition: Seems OK

Trunk Tgate Condition: Seems OK

Trunk Cargo Area Condition: Seems OK


Rear Bumper Condition: Seems OK

Tail Lights Condition: Seems OK

Rear Left Tire Condition: Seems OK

Rear Right Tire Condition: Seems OK

Right side




Right Rear Quarter Condition: Seems OK

Right Rear Door Condition: Seems OK

Right Front Door Condition: Seems OK

Right Fender Condition: Seems OK

Left side



Left Fender Condition: Major damage

Left Front Door Condition: Major damage

Left Rear Door Condition: Minor damage

Left Rear Quarter Panel Condition: Minor damage