

ALEXANDRIA ARMATURE WORKS

3025 COLVIN ST
ALEXANDRIA, VA 22314
703-370-3500 Office
703-370-9150 Fax

INVOICE

DATE	INVOICE NO.
12/4/2020	18524

BILL TO
HITEC POWER PROTECTION, INC. ATTN: ACCOUNTS PAYABLE 25707 SOUTHWEST FREEWAY ROSENBERG, TX 77471

SHIP TO
HITEC POWER PROTECTION c/o MICROSOFT/ACC3 44520 HASTINGS DR. ASHBURN, VA 20147

CONTRACT/P.O. NO.		TERMS	SHIP DATE	DUE DATE	SHIP VIA	JOB NO.	
1284819		Net 30	12/4/2020	1/3/2021		52708	
ITEM	DESCRIPTION				QTY	RATE	AMOUNT
Labor In-House	0.9KW ROBERT BIRKENBEUL PUMP MOTOR, 0.9KW 1395/1674 RPM, 250-280/440-480 VAC, MODEL# 5AP80M-4, SPEC ID# NR 692824 PUMP INFO: RICKMEIER R25/20 FL-Z-DB, 360116-0, R235006/157, 0011809501 SUPPLY OF LABOR FOR THE RECONDITIONING OF THE ABOVE PUMP MOTOR DESCRIPTION. WORK PERFORMED AS FOLLOWS: DISMANTLE MOTOR AND PERFORM PHYSICAL, MECHANICAL AND ELECTRICAL INSPECTIONS. FOUND: OIL INSIDE TERMINAL BOX; WORN-OUT SHAFT SEAL @ GEAR BOX; MECHANICAL FITS WITHIN TOLERANCE LIMITS; SCORING ON BEARINGS. SCOPE OF REPAIR: RECONDITION MOTOR; FIT AND INSTALL NEW BEARINGS, REPLACE SHAFT SEALS, RE-ASSEMBLE PUMP MOTOR AND PERFORM TEST-RUN AND PAINT.					332.50	332.50
Parts	SUPPLY OF NEW BEARINGS, SHAFT SEALS, CLEANING MATERIALS AND PAINT. Sales Tax					24.28 6.00%	24.28T 1.46

Received By _____ Date Rec'd 12-10-2020

Signature Jessica Ware

Printed Jessica Ware

Total \$358.24

ALEXANDRIA ARMATURE WORKS3025 COLVIN ST
ALEXANDRIA, VA 22314

703-370-3500 Office

703-370-9150 Fax

INVOICE

DATE	INVOICE NO.
12/4/2020	18523

BILL TO
HITEC POWER PROTECTION, INC. ATTN: ACCOUNTS PAYABLE 25707 SOUTHWEST FREEWAY ROSENBERG, TX 77471

SHIP TO
HITEC POWER PROTECTION c/o MICROSOFT/ACC3 44520 HASTINGS DR. ASHBURN, VA 20147

CONTRACT/P.O. NO.	TERMS	SHIP DATE	DUE DATE	SHIP VIA	JOB NO.
1284820	Net 30	12/4/2020	1/3/2021		52709

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
Labor In-House	0.55KW ELEKTRIM PUMP MOTOR, 1380/1660 RPM, TYP: SLG80-4A, 1.4 AMPS, 480 VAC, TEFC FRAME, SPEC ID# NR 470518 PUMPINFO: VAN WIJK & BOERMA POMPEN B.V. KF25 RFI, 00047958 SUPPLY OF LABOR FOR THE REPAIR OF THE ABOVE PUMP MOTOR DESCRIPTION. WORK PERFORMED AS FOLLOWS: DISMANTLE MOTOR AND PERFORM PHYSICAL, MECHANICAL AND ELECTRICAL INSPECTIONS. FOUND: OIL INSIDE TERMINAL BOX AND STATOR WINDINGS; MOTOR FAILED ELECTRICAL TESTS (FAILED SURGE TEST); WORN-OUT SHAFT SEAL @ GEAR BOX; MECHANICAL FITS WITHIN TOLERANCE LIMITS; SCORING ON BEARINGS. NOTE: MOTOR NEEDS REWIND: AAW RECOMMENDS REPLACEMENT OF MOTOR VS REWIND REPAIR WORK: CLEAN GEAR/PUMP SIDE; REPLACE SHAFT SEAL; INSTALL NEW REPLACEMENT MOTOR TO PUMP/GEAR; TEST-RUN AND PAINT	1	285.00	285.00
Parts	SUPPLY OF NEW REPLACEMENT MOTOR; ELEKTRIM P/N: 40MFM-3-.75-18; MOTOR FLANGE (41DM-FLA-80), SHAFT SEAL & CLEANING MATERIALS	1	318.65	318.65T
Freight	SHIPPING - PREPAY & ADD Sales Tax		30.91 6.00%	30.91 19.12

Received By _____ Date Rec'd 12-10-2020Signature Jessica WarePrinted Jessica Ware**Total** \$653.68