



Dept.	Technical reference	Created by	Approved by
	BeTrue3D.dk	Morten Nielsen	20-12-2017
The 4x 2.5mm holes should be threaded m3 You might want to make it 0.75-1mm thick		Document type	Document status
		Drawing	Working copy
		Title	DWG No.
		MotorShield Left	
Rev.	Date of issue	Sheet	
	13-02-2018	1/1	