



Dept.	Technical reference	Created by Morten Nielsen 20-12-2017	Approved by	
The 4x 2.5mm holes should be threaded m3		Document type	Document status	
		Title MotorShield Left	DWG No.	
		Rev.	Date of issue	Sheet 1/1