

Inlet Point Engineering

Storm Damage Inspection Report

Date of Inspection: June 01, 2025

Client: John Doe

Location: 123 Marina Lane, Jupiter, FL

Summary:

Following Hurricane Ian, a thorough inspection of the client's waterfront infrastructure was conducted. A drone flyover and visual structural assessment of the dock and seawall were performed to evaluate post-storm conditions.

Findings:

- Moderate damage to east-facing piling caps
- Evidence of soil displacement near seawall footer
- Debris accumulation at dock corners
- No signs of active undermining or collapse

Recommendations:

- Remove debris to prevent water blockage
- Monitor footer erosion after next tide event
- Replace damaged piling caps
- Schedule reinspection in 6 months

Inspector: Sarah Reynolds, E.I.

Contact: info@inletpointengineering.com