



MISTAKES OF v1:

- USD CD was not connected
- RTC RST (DS1391) causes ESP not to boot. Disconnect this signal or use DS1390
- S2 footprint is wrong

TITLE: LogBoard

AUTHOR: Renan R. Duarte

DOC NUMBER:

DATE: 15/10/2019 11:32

Sheet: 1/1

REV:

v1

Sheet: 1/1
