

**THE SEAT BUCKET
MECHANISM MUST
NOT BE OPERATED
FOR MORE THAN
1 MIN IN 8 MIN.**