



Crack number 1 (confidence score: 1.60%)
The detected crack is on wall component in this image.
Crack density: 0.16%
Crack width: -434.96 mm
Angle wrt horizontal line: -2.01 degree
Configuration: longitudinal
Position: Bottom fourths of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required