



Crack number 1 (confidence score: 12.39%)
The detected crack is on wall component in this image.
Crack density: 0.28%
Crack width: 10.94 mm
Angle wrt horizontal line: -105.33 degree
Configuration: transverse
Position: Middle fourths of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required