



Crack number 1 (confidence score: 12.39%)  
The detected crack is on wall component in this image.  
Crack density: 0.28%  
Crack width: 10.94 mm  
Angle wrt horizontal line: -105.33 degree  
Configuration: transverse  
Position: Middle fourths of the wall  
Severity index for this crack: 2  
Suggested corrective action: General repair but no detailed investigation required