


Crack number 1 (confidence score: 0.26%)
 The detected crack is on wall component in this image.
 Crack density: 0.01%
 Crack width: -22.79 mm
 Angle wrt horizontal line: -123.92 degree
 Configuration: shear
 Position: Right one fourth of the wall
 Severity index for this crack: 2
 Suggested corrective action: General repair but no detailed investigation required




Crack number 2 (confidence score: 0.20%)
 The detected crack is on wall component in this image.
 Crack density: 0.04%
 Crack width: 7.43 mm
 Angle wrt horizontal line: -87.61 degree
 Configuration: transverse
 Position: Right one fourth of the wall
 Severity index for this crack: 2
 Suggested corrective action: General repair but no detailed investigation required




Crack number 3 (confidence score: 0.16%)
The detected crack is on wall component in this image.
Crack density: 0.02%
Crack width: 4.38 mm
Angle wrt horizontal line: -89.21 degree
Configuration: transverse
Position: Right one fourth of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required



Crack number 4 (confidence score: 0.34%)
The detected crack is on wall component in this image.
Crack density: 0.01%
Crack width: 2.63 mm
Angle wrt horizontal line: -93.45 degree
Configuration: transverse
Position: Right one fourth of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required




Crack number 5 (confidence score: 0.84%)
The detected crack is on wall component in this image.
Crack density: 0.01%
Crack width: 4.55 mm
Angle wrt horizontal line: 6.88 degree
Configuration: longitudinal
Position: Bottom fourths of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required



Crack number 6 (confidence score: 0.12%)
The detected crack is on wall component in this image.
Crack density: 0.01%
Crack width: 3.77 mm
Angle wrt horizontal line: -92.94 degree
Configuration: transverse
Position: Right one fourth of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required



Crack number 7 (confidence score: 0.11%)
The detected crack is on wall component in this image.
Crack density: 0.00%
Crack width: 2.94 mm
Angle wrt horizontal line: -72.71 degree
Configuration: transverse
Position: Right one fourth of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required



Crack number 8 (confidence score: 0.11%)
The detected crack is on wall component in this image.
Crack density: 0.00%
Crack width: 1.32 mm
Angle wrt horizontal line: 12.16 degree
Configuration: longitudinal
Position: Top fourths of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required