


Crack number 1 (confidence score: 14.16%)  
 The detected crack is on wall component in this image.  
 Crack density: 2.15%  
 Crack width: 13.17 mm  
 Angle wrt horizontal line: 0.16 degree  
 Configuration: longitudinal  
 Position: Bottom fourths of the wall  
 Severity index for this crack: 4  
 Suggested corrective action: Detailed investigation required



Crack number 2 (confidence score: 0.82%)  
 The detected crack is on wall component in this image.  
 Crack density: 0.36%  
 Crack width: 16.34 mm  
 Angle wrt horizontal line: -117.32 degree  
 Configuration: shear  
 Position: Middle fourths of the wall  
 Severity index for this crack: 3  
 Suggested corrective action: Confirmation by manual visual inspection and general repair