



Crack number 1 (confidence score: 23.11%)
The detected crack is on wall component in this image.
Crack density: 0.05%
Crack width: 13.22 mm
Angle wrt horizontal line: -74.10 degree
Configuration: transverse
Position: Right one fourth of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required