


Crack number 1 (confidence score: 99.81%)  
The detected crack is on wall component in this image.  
Crack density: 0.17%  
Crack width: 10.78 mm  
Angle wrt horizontal line: -106.12 degree  
Configuration: transverse  
Position: Middle fourths of the wall  
Severity index for this crack: 2  
Suggested corrective action: General repair but no detailed investigation required



Crack number 2 (confidence score: 9.80%)  
The detected crack is on wall component in this image.  
Crack density: 0.16%  
Crack width: 15.12 mm  
Angle wrt horizontal line: -103.45 degree  
Configuration: transverse  
Position: Middle fourths of the wall  
Severity index for this crack: 2  
Suggested corrective action: General repair but no detailed investigation required