


Crack number 1  
The detected crack is on wall component in this image.  
Crack density: 0.25%  
Crack width: 6.14 mm  
Angle wrt horizontal line: 1.69 degree  
Configuration: longitudinal  
Position: Middle fourths of the wall  
Severity index for this crack: 2  
Suggested corrective action: General repair but no detailed investigation required



Crack number 2  
The detected crack is on wall component in this image.  
Crack density: 0.08%  
Crack width: 6.40 mm  
Angle wrt horizontal line: 9.51 degree  
Configuration: longitudinal  
Position: Middle fourths of the wall  
Severity index for this crack: 2  
Suggested corrective action: General repair but no detailed investigation required