



Crack number 1 (confidence score: 0.58%)
The detected crack is on wall component in this image.
Crack density: 0.01%
Crack width: 3.75 mm
Angle wrt horizontal line: -85.46 degree
Configuration: transverse
Position: Middle fourths of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required