


Crack number 1 (confidence score: 0.53%)
The detected crack is on wall component in this image.
Crack density: 0.25%
Crack width: 6.14 mm
Angle wrt horizontal line: 1.69 degree
Configuration: longitudinal
Position: Middle fourths of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required



Crack number 2 (confidence score: 0.13%)
The detected crack is on wall component in this image.
Crack density: 0.08%
Crack width: 6.40 mm
Angle wrt horizontal line: 9.51 degree
Configuration: longitudinal
Position: Middle fourths of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required