



Crack number 1 (confidence score: 3.03%)  
The detected crack is on wall component in this image.  
Crack density: 0.93%  
Crack width: 13.98 mm  
Angle wrt horizontal line: -3.27 degree  
Configuration: longitudinal  
Position: Top fourths of the wall  
Severity index for this crack: 2  
Suggested corrective action: General repair but no detailed investigation required