



Crack number 1 (confidence score: 0.88%)  
The detected crack is on wall component in this image.  
Crack density: 1.21%  
Crack width: 7.34 mm  
Angle wrt horizontal line: -1.78 degree  
Configuration: longitudinal  
Position: Middle fourths of the wall  
Severity index for this crack: 4  
Suggested corrective action: Detailed investigation required