


Crack number 1 (confidence score: 0.52%)  
The detected crack is on wall component in this image.  
Crack density: 0.06%  
Crack width: 8.40 mm  
Angle wrt horizontal line: 8.78 degree  
Configuration: longitudinal  
Position: Bottom fourths of the wall  
Severity index for this crack: 2  
Suggested corrective action: General repair but no detailed investigation required



Crack number 2 (confidence score: 0.71%)  
The detected crack is on wall component in this image.  
Crack density: 0.02%  
Crack width: 4.75 mm  
Angle wrt horizontal line: -128.45 degree  
Configuration: shear  
Position: Right one fourth of the wall  
Severity index for this crack: 2  
Suggested corrective action: General repair but no detailed investigation required