



Crack number 1 (confidence score: 5.15%)
The detected crack is on wall component in this image.
Crack density: 0.07%
Crack width: 12.07 mm
Angle wrt horizontal line: -109.33 degree
Configuration: transverse
Position: Left one fourth of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required