



Crack number 1

The detected crack is on wall component in this image.

Crack density: 0.28%

Crack width: 10.94 mm

Angle wrt horizontal line: -105.33 degree

Configuration: transverse

Position: Middle fourths of the wall

Severity index for this crack: 2

Suggested corrective action: General repair but no detailed investigation required