


Crack number 1 (confidence score: 1.21%)
 The detected crack is on wall component in this image.
 Crack density: 0.24%
 Crack width: 5.56 mm
 Angle wrt horizontal line: -85.46 degree
 Configuration: transverse
 Position: Left one fourth of the wall
 Severity index for this crack: 2
 Suggested corrective action: General repair but no detailed investigation required



Crack number 2 (confidence score: 0.88%)
 The detected crack is on wall component in this image.
 Crack density: 0.10%
 Crack width: 5.84 mm
 Angle wrt horizontal line: 0.95 degree
 Configuration: longitudinal
 Position: Middle fourths of the wall
 Severity index for this crack: 2
 Suggested corrective action: General repair but no detailed investigation required



Crack number 3 (confidence score: 8.42%)

The detected crack is on wall component in this image.

Crack density: 0.04%

Crack width: 5.81 mm

Angle wrt horizontal line: 9.88 degree

Configuration: longitudinal

Position: Middle fourths of the wall

Severity index for this crack: 2

Suggested corrective action: General repair but no detailed investigation required