



Crack number 1 (confidence score: 21.60%)

The detected crack is on wall component in this image.

Crack density: 0.17%

Crack width: 9.24 mm

Angle wrt horizontal line: -107.77 degree

Configuration: transverse

Position: Left one fourth of the wall

Severity index for this crack: 2

Suggested corrective action: General repair but no detailed investigation required