


Crack number 1 (confidence score: 3.97%)
The detected crack is on wall component in this image.
Crack density: 0.14%
Crack width: 15.93 mm
Angle wrt horizontal line: -108.42 degree
Configuration: transverse
Position: Left one fourth of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required



Crack number 2 (confidence score: 85.83%)
The detected crack is on wall component in this image.
Crack density: 0.11%
Crack width: 12.54 mm
Angle wrt horizontal line: -115.05 degree
Configuration: shear
Position: Left one fourth of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required



Crack number 3 (confidence score: 2.43%)

The detected crack is on wall component in this image.

Crack density: 0.13%

Crack width: 15.05 mm

Angle wrt horizontal line: -92.62 degree

Configuration: transverse

Position: Left one fourth of the wall

Severity index for this crack: 2

Suggested corrective action: General repair but no detailed investigation required