



Crack number 1 (confidence score: 94.66%)  
The detected crack is on wall component in this image.  
Crack density: 0.08%  
Crack width: 8.83 mm  
Angle wrt horizontal line: -106.91 degree  
Configuration: transverse  
Position: Middle fourths of the wall  
Severity index for this crack: 2  
Suggested corrective action: General repair but no detailed investigation required