



Crack number 1 (confidence score: 0.84%)

The detected crack is on wall component in this image.

Crack density: 0.01%

Crack width: 4.55 mm

Angle wrt horizontal line: -123.92 degree

Configuration: shear

Position: Right one fourth of the wall

Severity index for this crack: 2

Suggested corrective action: General repair but no detailed investigation required