


Crack number 1 (confidence score: 1.14%)
The detected crack is on wall component in this image.
Crack density: 0.12%
Crack width: 9.62 mm
Angle wrt horizontal line: -104.40 degree
Configuration: transverse
Position: Left one fourth of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required



Crack number 2 (confidence score: 6.16%)
The detected crack is on wall component in this image.
Crack density: 0.35%
Crack width: 8.02 mm
Angle wrt horizontal line: -108.81 degree
Configuration: transverse
Position: Left one fourth of the wall
Severity index for this crack: 2
Suggested corrective action: General repair but no detailed investigation required