



Hewlett Packard
Enterprise

HPE Proliant DL380 Gen10 - Front display port on Universal Media bay does not work

Table of contents

- Issue
- Environment
- Cause
- Resolution

Issue

HPE Proliant DL380 Gen10 - Front display port on Universal Media bay does not work

Environment

HPE Proliant DL380 Gen10 - Front display port on Universal Media bay does not work

Any operating system

Cause

HPE Proliant DL380 Gen10 - Front display port on Universal Media bay does not work

Resolution

Update the ILO 5 firmware version 2.70

Download Link : https://internal.support.hpe.com/connect/s/softwaredetails?language=en_US&softwareId=MTX_30dccc519d5a40dbba98f2673c&tab=Fixes

Reference SIE213538 and SIA4302941

